


A&E OVERSIGHT PROCESS FLOWCHART



Definitions (listed in descending order of anticipated work effort):

Perform	: Lead the work and assure delivery of the work products.
Review	: Evaluate work against T.O. and project requirements, provide recommendations , travel as needed.
Coordinate	: Assure communication of actions and recommendations to A/E, PM, CFT and others as needed.
Assist	: Contribute to receipt and review of work products and/or development and communication of recommendations.
Support	: As needed support to others for accomplishing the task (expected to be only in rare instances).